



Prop. N.E. BENTON

ENDERMERE GARAGE LIMITED

**Servicing
Welding
Mechanical
Repairs**

**Unit 11, Albion Industrial Estate,
Endemere Road, Coventry, CV6 5PY.**

Company No. 4717968

**Insurance
Work
Estimates**

Tel: 664260 & 685006

V.A.T. Reg. No. 273 7211 63

To: REGULATORY SERVICES

PERMIT REF. PPC/184

Date MARCH 15TH 2014



M.O.T.'S INCLUDING DIESELS & CATALYSTS
FIXED PRICE SERVICING - QUALITY BRAKE & FITTING SERVICE
MECHANICAL - WELDING & INSURANCE REPAIRS

FAST EFFICIENT SERVICE AT COMPETITIVE RATES

E: info@endemeregarage.co.uk | www.endemeregarage.co.uk

Tel: 024 7666 4260

Fax: 024 7668 5006

Unit 11, Albion Industrial Estate, Endemere Road, Coventry CV6 5PY



N. E. BENTON.



Untitled

Maintenance summery sheet [Period January 2013 - January 2014]

JAN 05 2013; Heater cleaned & smoke recorded [OK]

JAN 12 2013; Chimney stack secured & heater cabinet cleaned, used & tested [OK].

JAN 19 2013; Heater checked, oil pipe cleaned, tray cleaned, ash bagged up & tested [OK]

JAN 25 2013; Checked out, pan scrapped out to clear debris. Oil tank topped up & heater lit & tested [smoke OK].

FEB 11 2013; Heater cleaned , checked, smoke checked [OK].

FEB 18 2013; Heater cleaned, ash bagged checed out [OK].

FEB 25 2013; Heater cleaned, smoke tested [OK].

MAR 04 2013; Supply pipe cleaned out & tank cleaned [NOT USED].

MAR 11 2013; Dish scrapped clean, smoke tested [OK].

MAR 18 2013; Chimney stack re-secured at base & heater cleaned, inner & outer casing. Tested [OK].

MAR 25 2013; Heater cleaned, ash bagged, tested [OK] [Smoke clear].

APRIL 06 2013; Oil inlet tube replaced, now [ok] Supply [OK], Tested [OK].

APRIL 13 2013; Heater cleaned, ash bagged, oil spillage on floor cleaned, tested [OK].

APRIL 20 2013; Cabinet & oil spillage cleaned, combustion dish cleaned of scale. Tested [OK]. Smoke [OK].

APRIL 27 2013; NOT USED Cleaned & left.

NOVEMBER 13 2013; Heater checked, topped up with oil & tested & run [OK]. No faults recorded [OK].

NOV 23 2013; Heater cleaned , ash bagged.

DEC 03 2013; Heater checked & run seal of combustion chamber leaking & causing fumes.

Untitled

DEC 04 2013; New sealing cords fitted to combustion chamber,heater run & checked out [OK] By Graham.

DEC 13 2013; Heater cleaned, ash bagged,Combustion seals checked,smoke checked [OK].

DEC 20 2013;Heater stripped & cleaned,combustion dish , ADVISED Starting to break up. Heater tested [OK].

JAN 03 2014;Heater cleaned & ash bagged plus oil line cleaned & new combustion disc ordered. Smoke tested [OK].

JAN 10 2014;Heater stripped & cleaned.Newcombustion pan [modified] fitted, heater tested & smoke tested [OK] Outer cabinet also cleaned & floor standing area.

Staff trained to Operate Waste Oil Burner as follows:

Stephen Benton

Neville Benton

Graham White

No smoke emission problems recorded during period January 2013 – January 2014



N.E Benton